

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 9, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303


USNRC REGION I
ATLANTA, GEORGIA
83 JUN 20 AIO: 00

Re: McGuire Nuclear Station Units 1 and 2
Docket Nos. 50-369 and 50-370

Dear Mr. O'Reilly:

On May 27, 1983 your staff was notified that the Containment Pressure Control System monthly surveillance required by T.S. 4.3.2.1 Table 4.3-2 (Functional Unit #6) was not performed at the required interval for either Unit 1 or 2, and when performed it was found out of allowable limits. Pursuant to T.S. 3.3.2 which is reportable per T.S. 6.9.1.10(f), Reportable Occurrence Reports RO-369/83-30 (Unit 1) and RO-370/83-19 (Unit 2) were to have been submitted by June 9, 1983. However, analysis being performed necessary for the completion of the reports is not yet finished. The complete reports will be submitted by June 24, 1983.

Very truly yours,



Hal B. Tucker

PBN:jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

8306270094 830609
PDR ADOCK 05000369
S PDR

OFFICIAL COPY

TE 22

1/0