

USNRC REGION II
ATLANTA, GEORGIA

CP&L

USNRC REGION II
ATLANTA, GEORGIA

PRP
Helt
Docket File

83 JUN 21 A10:08

Carolina Power & Light Company

83 JUN 14 A12:10

Brunswick Steam Electric Plant

P. O. Box 10429

Southport, NC 28461-0429

FILE: B09-13510C

SERIAL: BSEP/83-1784

June 9, 1983

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8

Dear Mr. O'Reilly:

During an ongoing Unit No. 1 refueling outage on May 4 and 5, 1983, respective LCOs were generated on two fire doors in the Diesel Generator Building. One of these doors (Number 127) was rendered inoperable by accessing it to facilitate the performance of maintenance work, while the other door (Number 115) was found to be inoperable as a result of encountered high differential air pressure across the door which prevents self-closure. Plant Engineering has been requested to evaluate the differential air pressure problem affecting door Number 115. Until completion of the work affecting door Number 127 and resolution of the problem affecting door Number 115, appropriate stationed fire watches and the respective LCOs for these doors will remain in effect.

Very truly yours,

C. R. Dietz
C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/sgb/LETJ03

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

8306270098 830609
PDR ADOCK 05000325
S PDR

OFFICIAL COPY

IE22
110