



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
June 17, 1983

83 JUN 21 9:43

USNRC REGION I
ATLANTA, GEORGIA

FILE: B09-13510C
SERIAL: BSEP/83-1882


Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8

Dear Mr. O'Reilly:

During the ongoing Unit No. 1 refueling outage on May 13, 1983, an LCO was initiated for a fire door in the Diesel Generator Building. The door, number 213, was declared inoperable because of encountered high differential air pressure across the door which prevents automatic self-closure. Plant Engineering has been requested to evaluate the involved differential air pressure problem. Until the return of the subject door to operability and cancellation of the involved LCO, appropriate stationed fire watches will remain in effect.

Very truly yours,


C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/joh/LETJH1

cc: Mr. R. C. DeYoung
NRC Document Control Desk

8306270291 830617
PDR ADOCK 05000325
S PDR

OFFICIAL COPY

IE 22
1/0