

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

STATION MANAGER

March 11, 1983

RECEIVED
NRC

1983 MAR 17 PM 12:25

SCE

REGIONAL

TELEPHONE
(714) 492-7700

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-536

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-362
14-Day Follow-Up Report
Licensee Event Report No. 83-005
San Onofre Nuclear Generating Station, Unit 3

Reference: Letter, H. B. Ray (SCE) to R. H. Engelken (NRC),
dated February 28, 1983

The referenced letter provided you with confirmation of our prompt notification, pursuant to Section 6.9.1.12.b of Appendix A, Technical Specifications to Facility Operating License NPP-15 for San Onofre Unit 3, involving the snubbers in two Reactor Coolant Sample lines: one capable of being isolated by Containment Isolation valve 3HV508, and the other capable of being isolated by Containment Isolation valve 3HV517.

Pursuant to Section 6.9.1.12.b, this submittal provides the required 14-day follow-up report and a copy of Licensee Event Report (LER) No. 83-005.

If there are any questions regarding the above, please contact me.

Sincerely,

H. B. Ray

Enclosure: LER 83-005

cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Units 2 & 3)
R. J. Pate (USNRC Resident Inspector, San Onofre Units 2 & 3)

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission
Office of Management Information and Program Control

Institute of Nuclear Power Operations.

8303290329 830311
PDR ADDCK 05000362
PDR

IE-22
83-120