


TEXAS UTILITIES GENERATING COMPANY

2001 BRYAN TOWER DALLAS, TEXAS 75201-3050

R. J. GARY  
EXECUTIVE VICE PRESIDENT  
AND GENERAL MANAGER

June 21, 1983  
TXX-3692



Mr. G. L. Madsen, Chief  
Reactor Project Branch 1  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76012

Docket Nos.: 50-445  
50-446

COMANCHE PEAK STEAM ELECTRIC STATION  
STRUT JAMMING DEVICES  
QA FILE: CP-83-13, SDAR-113  
FILE NO.: 10110

Dear Mr. Madsen:

On May 26, 1983 we verbally informed your Mr. R. G. Taylor of a deficiency regarding jam nuts on rigid struts which are not adequately installed to prevent rotation of the strut barrel.

We have completed our investigation and concluded that the matter is not reportable under 10 CFR 50.55(e). Records supporting this determination are available for your Inspector's review at the CPSES site.

Very truly yours,

A handwritten signature in cursive script that reads "R. J. Gary".

RJG:ln

cc: NRC Region IV - (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

8306300088 830621  
PDR ADOCK 05000445  
S PDR

IF 27  
1/0