

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

USNRC REGION II
ATLANTA, GEORGIA

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

83 JUN 27 P 1:10

June 20, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 2
Docket No. 50-370

Dear Mr. O'Reilly:

My letter of June 10, 1983 notified you that all information for a 30-day Reportable Occurrence (RO-370/83-18), which was originally to be submitted on that date, was not yet available and that the report would be submitted by June 20, 1983. This Reportable Occurrence concerned T.S. 3.3.3.8, "The radio-active liquid effluent monitoring instrumentation channels shown in Table 3.3-12 shall be operable...", which was violated on May 13, 1983. However, it has since been determined that this incident is not reportable (in accordance with T.S. 3.3.2.8 Action c.), and therefore no report will be submitted.

Very truly yours,

H.B. Tucker 1-100

Hal B. Tucker

PBN:jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

OFFICIAL COPY

IE 22

1/1

8306300171 830620
PDR ADOCK 05000370
S PDR