



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 22, 1983

W3I83-0226
Q-3-A35.07.68

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 68
"Spurious ESFAS Actuation"
Fourth Interim Report



REFERENCE: LP&L letter W3I83-0195 dated May 30, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 24, 1983.

All required modifications have now been completed, however testing is still underway. A Final Report will therefore be submitted to the USNRC by August 26, 1983.

Very truly yours,

Thomas F. Gerits for

F. J. Drummond
Project Support Manager - Nuclear

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8306300188 830622
PDR ADOCK 05000382
S PDR

IE 27
1/0