



Nuclear Division
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 456-6000

July 5, 1983

Director of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Attn: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing
Washington, DC 20555

Reference: Beaver Valley Power Station, Unit No. 1
Docket No. 50-334, License No. DPR-66
Inadvertant Safety Injection During Cooldown

Gentlemen:

By letter dated December 28, 1979, A. Schwencer to C. N. Dunn, the Division of Operating Reactors documented completion of a generic bounding review on inadvertent safety injection during cooldown. It was concluded that a facility could withstand more than fifty inadvertent ECCS actuations.

It was recently requested by our Resident Inspector that we review this NRC generic report to assure ourselves that Beaver Valley, Unit No. 1 is adequately bounded by the generic review. Since this document formed the basis for satisfying the licensing action on inadvertent safety injections, it is considered appropriate that we perform this review. We respectfully request that a copy of this generic review performed by the Division of Operating Reactors be forwarded to my office for the purpose of completing this review.

Very truly yours,

J. J. Carey
Vice President, Nuclear

Attachment

cc: Mr. W. M. Trostoski, Resident Inspector
U. S. Nuclear Regulatory Commission
Beaver Valley Power Station
Shippingport, PA 15077

U. S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, DC 20555

Handwritten: A001
110