

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

RECEIVED
NRC

1983 JUL 11 PM 12:21

July 1, 1983

ANPP-24229-RQT/BSK

REGION V FILE

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Time Extension for Report - DER 83-25
A 50.55(e) Potentially Reportable Deficiency Relating To
Instrumentation Tubing Does Not Have A Boundary Class Break
As Required
File: 83-019-026, D.4.33.2

Reference: A) Telephone conversation between P. Narbut and G. Duckworth
on April 21, 1983.
B) ANPP-23911, dated May 26, 1983 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by June 30, 1983.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by August 19, 1983, at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr.

E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

by B. A. Adewi

EEVBJr/RQT:ru

cc: See Page 2

8307180221 830701
PDR ADCK 05000528
S PDR

1/0 IF-27

U. S. Nuclear Regulatory Commission
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
G. C. Andognini
J. A. Roedel
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. R. Bynum
P. P. Klute/D. D. Green
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway - Suite 1500
Atlanta, Georgia 30339