

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

10	1	8											14	15											25	26	1	1	1	1	1	4	15	57	CAT	58																
			LICENSEE CODE										LICENSE NUMBER																				LICENSE TYPE																			
10	1	8	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE																			
10	1	8	60										61										68										74										80									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

On 2/22/83, while in Mode 1 at 92% full power, the steam driven emergency feedwater (EFW) pump 2P-7A would not attain rated speed or discharge pressure when surveillance testing was being performed. EFW pump 2P-7B and its associated train were operable. This is similar to LER (50-368) 80-039. This is reportable per Technical Specification (T.S.) 6.9.1.9.b.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The cause of this occurrence was setpoint drift in the speed controller. The converter gain on the speed

1 1 | controller was adjusted to cause the pump to run at desired speed. The pump was returned to service within

1 2 | the constraints of T.S. 3.7.1.2. The component involved was an EG-M Control Box manufactured by the Woodward

1 3 | Governor Company.

1 4 |

7 8 9

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	1	28	0	9	2	29	1	NA
7	8	9	10	12	13	44	45	1	B
								Routine Surveillance	

ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	2	34	1	135	1	36
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES										
NUMBER					TYPE		DESCRIPTION			
1	1	7			0	0	0	137	Z 138	NA
7				8	9			11	12	13

PERSONNEL INJURIES										80
NUMBER					DESCRIPTION					
1	2	3	4	5	6	7	8	9	10	
1	1	8			0	0	0	40		NA
7					9			1		
										41

	9	11	12		80
	LOSS OF OR DAMAGE TO FACILITY				
	TYPE		DESCRIPTION		
[1]	[9]	[Z [42]	NA		143

PUBLCITY		ISSUED		DESCRIPTION		NRC USE ONLY													
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26

NAME OF PREPARER Patrick C. Rogers and Phillip B. Wade

PHCNE: (501) 964-3100

8304040227 830324
PDR ADDCK 05000368
S PDR