




Omaha Public Power District

1623 HARNEY ■ OMAHA, NEBRASKA 68102 ■ TELEPHONE 536-4000 AREA CODE 402

December 17, 1982

LIC-82-398



Mr. W. C. Seidle, Chief
Reactor Project Branch 2
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Reference: Docket No. 50-285

Dear Mr. Seidle:

Emergency Preparedness Appraisal Followup Inspection

During the week of November 8-12, 1982, an inspection team from your office conducted a followup inspection of the Fort Calhoun Station emergency preparedness program. During the exit on November 12, 1982, the one significant deficiency noted was related to an inconsistency in the performance of Surveillance Test ST-RM-3, "Emergency Plan Instruments and Equipment". There was an inconsistency regarding the actual location versus the location of equipment as listed in ST-RM-3. For example, ST-RM-3 indicated that the emergency locker in the Emergency Operations Facility (EOF) included three self-contained breathing apparatuses (SCBA's) when, in fact, they were hung on the wall near the locker. As discussed by telephone between Mr. Montgomery of your staff and Mr. Patterson of the District on November 29, 1982, ST-RM-3 has been revised to accurately reflect the actual locations of all emergency equipment. Additionally, Table H-1 of the Radiological Emergency Response Plan (RERP) has also been revised to reflect these changes. As requested by Mr. Montgomery, please find attached the revised ST-RM-3 (Revision 16) and Table H-1 (Revision 1).

Sincerely,

W. C. Jones
Division Manager
Production Operations

WCJ/TLP:jmm

Attachments

cc: LeBoeuf, Lamb, Leiby & MacRae
Mr. J. L. Montgomery, NRC Emergency Preparedness Analyst
Mr. E. G. Tourigny, NRC Project Manager
Mr. L. A. Yandell, NRC Senior Resident Inspector