



# MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

March 17, 1983

JAMES P. McGAUGHY, JR.  
ASSISTANT VICE PRESIDENT

CORRECTED COPY

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 2900  
Atlanta, Georgia 30303

In previous letter the  
Special Report number was  
typed as 83-003/01; it  
should be 83-003/0.  
Previous letter noted  
attachment; attachment notation  
not needed.

Attention: Mr. J. P. O'Reilly, Regional Administrator


Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Special Report 83-003/0 -  
Fire Door Alarmed and Would  
Not Reset  
AECM-83/0181

On February 8, 1983, during cold shutdown, fire door OC414 (Control Building, Stairway OC001) alarmed and would not reset after Operations verified the door was closed. A Limiting Condition for Operation (LCO) was entered and an hourly fire watch was established as required by Technical Specification 3.7.7.

Maintenance personnel found fire door OC414 inoperable due to a malfunction of the latch bolt. The latch mechanism was reworked and the door was functionally tested to be operable. The LCO was in effect for 7 days and 16 hours, therefore, this letter is submitted as a Special Report pursuant to Technical Specification 6.9.2. This is a final report.

Yours truly,

  
FOR J. P. McGaughy, Jr.

JPM:sap

cc: (See Next Page)

8304050513 830317  
PDR ADOCK 05000416  
S PDR

OFFICIAL COPY  
I-E 19

MISSISSIPPI POWER & LIGHT COMPANY

AECM-83/0181

Page 2

cc: Mr. J. B. Richard  
Mr. R. B. McGehee  
Mr. T. B. Conner  
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555