

Corrected Copy



A Centennial Energy Company

EDISON PLAZA  
300 MADISON AVENUE  
TOLEDO, OHIO 43652-0001

August 26, 1994

DSR-94-00283

File No. E2.30.2.2  
Docket Number 50-346  
License Number NPF-3United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Subject: July 1, 1993 - June 30, 1994, Radioactive Effluent Release Report

Gentlemen:

Enclosed are two copies of the July 1, 1993 - June 30, 1994, Radioactive Effluent Release Report for the Toledo Edison Company, Davis-Besse Nuclear Power Station, Unit No. 1.

This report meets the requirement of Regulatory Guide 1.21, Davis-Besse Technical Specifications, Section 6.9.1.11 and the Davis-Besse Offsite Dose Calculation Manual, Section 7.2. All radioactivity released in gaseous and liquid effluents was well within the concentration and release limits specified in the Offsite Dose Calculation Manual.

Very truly yours,

J. K. Wood  
Plant Manager

JAL/ekg

Enclosure

cc: J. B. Martin, Regional Administrator, NRC Region III  
S. Stasek, DE-1 NRC Senior Resident Inspection  
L. L. Gundrum, NRC Project Manager  
Utility Radiological Safety Board

IE48 1/1

Diskette  
to: Files



A Centerior Energy Company

EDISON PLAZA  
300 MADISON AVENUE  
TOLEDO, OHIO 43652-0001

DSR-94-00283

File No. E2.30.2.2  
Docket Number 50-346  
License Number NPF-3

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Subject: July 1, 1993 - June 30, 1994, Radioactive Effluent Release Report

Gentlemen:

Enclosed are two copies of the July 1, 1993 - June 30, 1994, Radioactive Effluent Release Report for the Toledo Edison Company, Davis-Besse Nuclear Power Station, Unit No. 1.

This report meets the requirement of Regulatory Guide 1.21, Davis-Besse Technical Specifications, Section 6.9.1.11 and the Davis-Besse Offsite Dose Calculation Manual, Section 7.2. All radioactivity released in gaseous and liquid effluents was well within the concentration and release limits specified in the Offsite Dose Calculation Manual.

Very truly yours,

J. K. Wood  
Plant Manager

J:ekg

Enclosure

cc: J. B. Martin, Regional Administrator, NRC Region III  
S. Stasek, DB-1 NRC Senior Resident Inspection  
L. L. Gundrum, NRC Project Manager  
Utility Radiological Safety Board

020001

IF48  
11  
Inspected to: Fisher