



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

March 28, 1983

L. V. MAURIN  
Vice President Nuclear Operations

W3I83-0103  
Q-3-A35.07.64

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 64  
"Safety Injection Tanks, Discharge Flow Rates"

REFERENCE: LP&L letter W3P82-3312 dated October 29, 1982, L. V. Maurin  
to John T. Collins

Dear Mr. Collins:

At the present time, Ebasco Engineering is reviewing the plant safety  
analyses performed by Combustion Engineering. A final report will, therefore,  
be delayed until April 27, 1983.

Very truly yours,

*L. V. Maurin*  
L. V. Maurin

IE-27

LVM/MAL:keh

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555  
  
2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson