

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CAS05200-00000-0034111145
7 8 9 14 15 25 26 30 37 CAT 58

CON'T
01 L605000361702248380325839
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With both Units 2 and 3 in Mode 5, the door latch for door C3-67 between the Control
03 Room and the north elevation 30' Cable Risers Gallery was discovered to be jamming
04 intermittently and preventing the door from latching closed. Since this door is
05 required to be closed during CREACUS actuation to provide sufficient positive
06 pressure in the Control Room, Trains A and B CREACUS were declared inoperable at 1430.
07 Since there were no operations involving core alterations or positive reactivity
changes taking place at the time, LCO 3.7.5, Action Statement 'b' was satisfied.
08 Public health and safety were not affected.

09 SG11 E12 B13 XXXXXX14 Z15 Z16
7 8 9 10 11 12 13 18 19 20
17 LER/RO 83 020 03 L 0
7 8 9 21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN X18 FUTURE ACTION X19 EFFECT ON PLANT Z20 SHUTDOWN METHOD Z21 HOURS 0000 ATTACHMENT SUBMITTED N23 NRPD-4 FORM SUB. N24 PRIME COMP. SUPPLIER A25 COMPONENT MANUFACTURER X99926
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Intermittent jamming of the door was caused by excessive use. The door hardware
11 appeared to be too light for the door. In accordance with Special Order 83-18,
12 emergency maintenance was performed. Trains A and B CREACUS were declared operable
13 at 0230 on 2/25/83 after posting a guard at the door to ensure proper latching after
each entry or exit. An extensive maintenance program is currently being developed to
14 prevent recurrence of this event. See also LER 83-020.

15 B28 00029 N/A A31 Fire watch tour 32
7 8 9 10 12 13 44 45 46 80
ACTIVITY CONTENT Z33 Z34 AMOUNT OF ACTIVITY N/A LOCATION OF RELEASE N/A
7 8 9 10 11 44 45 80
PERSONNEL EXPOSURES NUMBER 00037 TYPE Z38 DESCRIPTION N/A
7 8 9 11 12 13 80
PERSONNEL INJURIES NUMBER 00040 DESCRIPTION N/A
7 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY TYPE Z42 DESCRIPTION N/A
7 8 9 10 80

20 N44 N/A 8304110218 830325 PDR ADOCK 05000361 PDR
7 8 9 10 68 69 80
PUBICITY ISSUED DESCRIPTION N/A NRC USE ONLY

NAME OF PREPARER

H.B. RAY

PHONE: 714-492-7700