

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M A P P S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 - 0 2 9 3 7 0 2 2 5 8 3 8 0 3 2 4 8 2 9  
7 8 9 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During routine inspection of the Standby Gas Treatment System (SGTS) the "B" SGTS  
0 3 filter train was found inoperable due to the charcoal being water soaked. The  
0 4 manual valve for the automatic fire deluge system was immediately closed, a firewatch  
0 5 established and testing of the redundant 'A' SGTS initiated. This event caused no  
0 6 threat to the public health and safety.  
0 7  
0 8

0 9 SYSTEM CODE A B 11 CAUSE CODE B 12 CAUSE SUBCODE A 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE F 15 VALVE SUBCODE X 16  
7 8 9 10 11 12 13 14 15 16 17  
17 LER/RO REPORT NUMBER 8 3 21 22 EVENT YEAR 8 3 23 24 SEQUENTIAL REPORT NO. 0 1 1 1 25 26 OCCURRENCE CODE 0 3 27 28 REPORT TYPE L 29 30 REVISION NO. 0 31 32  
ACTION TAKEN A 18 FUTURE ACTION F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPSD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER X 25 COMPONENT MANUFACTURER A 1 1 9 8 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Incorrect installation details were provided with the design package for the Alison  
1 1 Control solenoid vlv.#191004. The charcoal filters were replaced and the fire watch  
1 2 will be continued until the valve can be relocated following the manufacturer's  
1 3 recommended installation instructions.  
1 4

1 5 FACILITY STATUS E 28 % POWER 0 9 9 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Routine Inspection 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NRC USE ONLY

G. G. Whitney

PHONE: 617-746-7900