

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY
STATION MANAGER

March 30, 1983

RECEIVED
NRC
1983 APR -4 AM 8:58
SCE
REGISTRY
TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator


Dear Sir:

Subject: Docket No. 50-361
30-Day Follow-Up Reports
Licensee Event Report Nos. 82-094 and 82-103
San Onofre Nuclear Generating Station, Unit 2

Reference: Letter, H.B. Ray (SCE) to R.H. Engelken (NRC),
dated November 30, 1982

This letter provides the follow-up to the referenced reports which were made in accordance with Section 6.9.1.13.b of Appendix A to Facility Operating License NPF-10 for San Onofre, Unit 2. The reported events involve Limiting Condition for Operation (LCO) 3.6.3. Revised copies of LER's 82-094 and 82-103 are enclosed.

Sincerely,



Enclosures: LER 82-094, 82-103

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)

8304110481 830330
PDR ADDCK 05000361
S PDR

IE-22
83-151