


Alabama Power Company  
40 Inverness Center Parkway  
Post Office Box 1295  
Birmingham, Alabama 35201  
Telephone 205 868-5086

J. D. Woodard  
Vice President-Nuclear  
Farley Project

April 19, 1991



Docket No. 50-348


U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555

Joseph M. Farley Nuclear Plant - Unit 1  
Special Report No. 91-002, Fire Barrier Penetration  
Non-Functional For More Than Seven Days

Gentlemen:

In accordance with the requirements of Technical Specification 3.7.12, the enclosed Special Report No. 91-002, Unit 1, is submitted.

Respectfully submitted,


  
J. D. Woodard

JDW/BHW:map 0099

Enclosure

cc: Mr. S. D. Ebner  
Mr. S. T. Hoffman  
Mr. G. F. Maxwell

9104230483 910419  
PDR ADOCK 05000348  
S FDR

IE22  
  
4/1

Special Report No. 91-002, Unit 1  
Fire Barrier Penetration Non-Functional  
For More Than Seven Days

At 0820 on March 27, 1991, fire door number 218 was removed to support outage activities inside room 226 in the auxiliary building. Due to the scope of the work, the door was not replaced after seven days. Technical Specification 3.7.12 requires that all non-functional fire barrier penetrations be restored to functional status within seven days or a Special Report must be submitted within the next 30 days. Therefore, this Special Report is being submitted.

Fire door 218 will be replaced and declared functional on approximately April 17, 1991. Technical Specification action requirements are being met for the fire door.