



April 4, 1983

Log No. K83-541

File: RR 2 (NP-33-81-03,
NP-33-81-86,
NP-33-82-79,
NP-33-83-11)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of revised NRC Form 366 which is a part of the following Davis-Besse Unit 1 Licensee Event Reports: 81-004, 81-073, 82-064, and 83-008. These forms have been revised to change the information in block 24, NPRD-4 Form Submitted.

There has been no change to the supplemental information sheets included with each Licensee Event Report. Therefore, please replace only the Licensee Event Report NRC Form 366 in each of the above mentioned reports with the attached revisions, retaining the respective supplemental information sheets.

Yours truly,

Terry D. Murray

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Tom Peebles
NRC Resident Inspector
Encl: 1 copy

TE22