

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | s | c | v | c | s | h | 2 | b | 0 | - | b | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | b | 0 | 0 | 4 | 57 | CAT | 58 | 5

7 8 9 14 15 25 26 30 57 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T

01 REPORT SOURCE L 6 0 5 0 0 0 3 9 5 7 0 3 0 5 8 3 8 0 3 3 1 8 3 9

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On March 5, 1983, at 1815 hours, with the Plant in Mode 1, Fire Detector System

0 3 | Control Room alarm capability was lost for Intermediate Building zones AA, BB, and

0 4 | CC; and for Diesel Generator Building zones DG (427), DG (436). These detectors

0 5 | are required to be operable per Technical Specification 3.3.3.7. There were no

0 6 | adverse consequences because a fire watch patrol was established within one (1)

0 7 | hour as required by Action Statement (a) of Technical Specification 3.3.3.7.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Cause was determined to be a blown fuse on an instrument card. The fuse was

1 1 replaced, and the detectors were returned to operable status on March 5, 1983,

1 2 at 1945 hours.

1 3

1 4

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
1	5	0	N/A	A	Operator Observation

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 7 33 34 N/A 45 N/A 45

PERSONNEL EXPOSURES			
NUMBER	TYPE	DESCRIPTION	
1 7	37	38	N/A

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0000	N/A

8304130170

1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5															

ISSUED		PUBLICATION DESCRIPTION		NRC USE ONLY									
2	0	N	44	N/A									

NAME OF PREPARER

A. R. Koon, Jr

PHONE: (803) 345-5209