



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

April 7, 1983

JAMES P. McGAUGHY, JR.
VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Special Report 83-017/0 - Fire
Door OC313 Inoperable
AECM-83/0211

On March 1, 1983, the latch to fire door OC313 in the Control Building was discovered by an operator to be damaged resulting in an alarmed condition for that fire zone. Technical Specification 3.7.7 requires the door and supervisory alarm to be operable at all times. An hourly fire watch was established and will be maintained while the door is inoperable in accordance with Technical Specification 3.7.7.

The latch mechanism is expected to be repaired by April 30, 1983. This is a Special Report submitted pursuant to Technical Specification 6.9.2.

Yours truly,

James P. McGaughy, Jr.
FOR J. P. McGaughy, Jr.

JPM:sap

cc: Mr. J. B. Richard
Mr. R. B. McGehee
Mr. T. B. Conner
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8304130382 830407
PDR ADDCK 05000416
S PDR

OFFICIAL COPY

1522