



## Nebraska Public Power District

NEBRASKA PUBLIC POWER DISTRICT  
P. O. BOX 499  
1414 - 15TH STREET  
COLUMBUS, NE 68602-0499

GUY R. HORN  
Vice-President, Nuclear  
(402) 562-3518

NLS940014  
September 21, 1994

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

Subject: Followup Response to Inspection Report No. 50-298/94-04  
Cooper Nuclear Station  
NRC Docket No. 50-298, DPR-46

Reference: Letter from G. R. Horn (NPPD) to USNRC dated July 6, 1994, "Reply to Notice of Violation, NRC Inspection Report No. 50-298/94-04"

Gentlemen:

The Nebraska Public Power District (District) provided its reply in the reference to the two violations regarding the Service Water System identified in the subject inspection report. One of the violations concerned the lack of updating design basis documents for the design temperature of the Service Water System. In the referenced response to that violation, the District stated that a document search/upgrade to ensure the 90°F Service Water design temperature is properly incorporated into all applicable design input documents would be performed. The District went on to say that this effort, including necessary procedure revisions, would be complete by August 31, 1994.

The District has performed a document search to upgrade the Service Water design temperature to 90°F. To date, 160 document changes have been submitted for updates including Updated Safety Analysis Report (USAR) revisions. However, seven documents that have been identified as requiring changes have not been submitted as of August 31, 1994; these documents are as follows:

- Vendor Manual 0070 - RHR Heat Exchangers
- Vendor Manual 0245 - Emergency Diesel Generators
- Vendor Manual 1025 - GE Manual for CNS
- Cooper Bessemer DWG. KSV-46-5
- Cooper Bessemer Dwg. KSV-47-8
- Cooper Bessemer Dwg. KSV-47-9
- Service Water and RHR Service Water Design Criteria Document DCD 3

The District was unable to meet the original completion date of August 31, 1994, due to the numerous start-up issues that have been identified since the reference was submitted. The District has allocated proper manpower requirements and plans to complete the document search/upgrade and make any necessary procedure revisions by October 31, 1994.


9409270224 940921  
PDR ADDCK 05000298  
PDR

JEV 10

NLS940014  
September 21, 1994  
Page 2 of 2

If you have any questions or require any additional information concerning this subject, please contact me at this office.

Sincerely,



G. R. Horn  
Vice-President, Nuclear

GRH/tja trir9404i

cc: NRC Regional Office  
Region IV  
Arlington, TX

NRC Resident Inspector  
Cooper Nuclear Station

NPG Distribution