

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

RECEIVED  
NRC

1983 APR -7 AM 10:37

SCE

REGION VILL

TELEPHONE  
(714) 492-7700

H. B. RAY  
STATION MANAGER

April 1, 1983

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator


Dear Sir:

Subject: Docket No. 50-361 and 50-362  
30-Day Report  
Licensee Event Report No. 83-024 (Docket 50-361)  
San Onofre Nuclear Generating Station, Units 2 & 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating Licenses NPF-10 and NPF-15 for San Onofre Units 2 and 3, respectively, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) 83-024 addressing an occurrence involving the Emergency Chilled Water System. Since this occurrence involves a shared system between Unit 2 and Unit 3, in accordance with NUREG-0161, a single LER for Unit 2 (Docket 50-361) is enclosed.

If there are any questions regarding this event, please contact me.

Sincerely,



Enclosure: LER 83-024

April 1, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)

R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)