

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

STATION MANAGER

April 1, 1983

RECEIVED
1983

1983 APR -7 AM 10:35

SCE

REGION V

TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator


Dear Sir:

Subject: Docket No. 50-362
30-Day Report
Licensee Event Report No. 83-024
San Onofre Nuclear Generating Station, Unit 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre, Unit 3, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.6.3 associated with containment isolation valves. Enclosed LER 83-024 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding this event, please contact me.

Sincerely,



Enclosure: LER 83-024, Unit 3

8304140211 830401
PDR ADOCK 05000362
S PDR

IE-19

April 1, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)

R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)