



Duquesne Light

Nuclear Construction Division
Robinson Plaza, Building 2, Suite 210
Pittsburgh, PA 15205

2NRC-3-013
(412) 787-5141
(412) 923-1960
Telecopy (412) 787-2629

March 17, 1983

United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

ATTENTION: Mr. Richard W. Starostecki
Division of Project and Resident Programs

SUBJECT: Beaver Valley Power Station - Unit No. 2
Docket No. 50-412
USNRC IE Inspection Report No. 50-412/83-01

Gentlemen:


On February 18, 1983, Duquesne Light Company (DLC), Beaver Valley Power Station - Unit No. 2 (BVPS-2) received NRC Inspection 83-01, with the findings being one violation (83-01-01) and four unresolved items (83-01-02, 83-01-03, 83-01-04, and 83-01-05). In the cover letter of the report, the NRC indicated that DLC must respond to violation 83-01-01 as well as unresolved items 83-01-03, -04, and -05 within thirty days of the date of the Notice.

BVPS-2 has been working on the resolution to these items. The complexity of the issue has been determined to require extensive review between the licensee, architect/engineer and NSSS vendor. DLC considers this to be a significant issue, and in order to provide for an effective evaluation, BVPS-2 is requesting an extension to the response time for inspection 50-412/83-01 until May 4, 1983.

The Resident Inspector for BVPS-2 has been and will be informed of the progress of BVPS-2 efforts in the Resolution of these items.

DUQUESNE LIGHT COMPANY

By


E. J. Woolever
Vice President

JMM/wjs

cc: Mr. G. Walton, NRC Resident Inspector
Ms. L. Lazo, Project Manager
NRC Document Control Desk

8304140277 830408
PDR ADOCK 05000412
Q PDR