



**ENTERGY**

Entergy Operations, Inc.

P.O. Box B

Kilgus, LA 70086

Tel 504 739 6774

**R. F. Burski**

Director

Nuclear Safety

Waterford 3

W3F1-94-0154

A4.05

PR

September 23, 1994

Mr. Leonard J. Callan  
Regional Administrator, Region IV  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

Subject: Waterford 3 SES  
Docket No. 50-382  
License No. NPF-38  
Reactor Operator License

Dear Mr. Callan:

Listed below is an individual currently included in the U.S. Nuclear Regulatory Commission Operator Licensing Tracking System who no longer requires a senior reactor operator license at Waterford 3 SES. The change in license requirement status is due to the individual changing job responsibilities within the company.

Appl. Dock. Number	Name	License Type	License Number
55-40527	Vinci, Donald W.	SOP	43539

270071

9409280268 940923  
PDR ADDCK 05000382  
V PDR

ma310

Reactor Operator License


W3F1-94-0154

Page 2

September 23, 1994

If you have any questions concerning the above, please contact  
O.P. Pipkins at (504) 739-6707.

Very truly yours,

A handwritten signature in cursive script, appearing to read "D. Win for R.F. Burski".

R.F. Burski  
Director  
Nuclear Safety

RFB/OPP/ssf

cc: R.B. McGehee  
N.S. Reynolds  
NRC, Document Control Desk  
NRC Resident Inspectors Office

Reactor Operator License


W3F1-94-0154

Page 2

September 23, 1994

If you have any questions concerning the above, please contact  
O.P. Pipkins at (504) 739-6707.

Very truly yours,

A handwritten signature in cursive script, appearing to read "D. Wain for R.F. Burski".

R.F. Burski  
Director  
Nuclear Safety

RFB/OPP/ssf

cc: R.B. McGehee  
N.S. Reynolds  
NRC, Document Control Desk  
NRC Resident Inspectors Office