



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

April 6, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137


Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm a verbal report given to Mr. E.R. Swanson of your staff at 1225 hours on this date. At that time, Mr. Swanson was advised that the Unit 1 Halon System had been declared inoperable on April 5, 1983, following completion of a nonroutine concentration test. It was also noted that the Unit 2 Halon System is being administratively considered inoperable until the test can be performed in that unit.

A followup report will be submitted within fourteen days in accordance with Unit 1 Technical Specification Section 6.9.1.12.

Sincerely,

  
W.G. Smith, Jr.  
Plant Manager

/bab

cc: John E. Dolan  
R.S. Hunter  
M.P. Alexich  
R.F. Kroeger  
B. Germano  
E.R. Swanson/N.E. DuBry RO:III  
R.C. Callen, MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee, EPRI  
INPO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (40 copies)  
Dir., MIPC (4 copies)

APR 11 1983

IE29

8304150406 830406  
PDR ADDCK 05000315  
PDR  
S