

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

RECEIVED  
NRC

SCE

PM 1:26

REGIONAL

TELEPHONE  
(714) 492-7700

*jm*  
H. B. RAY  
STATION MANAGER

April 6, 1983

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator


Dear Sir:

Subject: Docket No. 50-362  
30-Day Follow-Up Report  
Licensee Event Report no. 83-027  
San Onofre Nuclear Generating Station, Unit 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre, Unit 3, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.3.3.6 associated with accident monitoring instrumentation. Enclosed LER 83-027 addresses this event, including corrective actions and measures to prevent recurrence.

If you have any questions regarding the above, please contact me.

Sincerely,



Enclosure: LER 83-027, Unit 3

8304180209 830406  
PDR ADOCK 05000362  
S PDR

IE-22  
83-161

April 6, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)  
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)