

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y J A F 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 0 3 2 2 8 3 8 0 4 0 6 8 3 9

DOCKET NUMBER 60 61 EVENT DATE 68 69 REPORT DATE 74 75

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During normal operation, while conducting surveillance testing of the Low Pressure

0 3 Main Steam Line Switches, 02-PS-134B, the setpoint was found less conservative than

0 4 \geq 825 PSIG as required by T.S. Table 3.2-1. The found value was 823.5 PSIG. Other

0 5 trip channels of the same parameter were available and had setpoints within T.S.

0 6 requirements. The event did not represent a significant hazard to the public health

0 7 and safety.

0 8

0 9

SYSTEM CODE C D 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16

LER/RO REPORT NUMBER 17 EVENT YEAR 8 3 SEQUENTIAL REPORT NO. 0 1 3 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

ACTION TAKEN E 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER 8 0 6 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Instrument drift was the cause. Corrective action consisted of immediate adjustment

1 1 of the setpoint within the required value and increasing the surveillance frequency

1 2 of the switch in order to trend observation. No additional action is required.

1 3

1 4

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY DESCRIPTION N 44 NA 45

ISSUED 2 0 NA 46

8304180295 830406
PDR ADDCK 05000333
S PDR

NRC USE ONLY
315-342-3840

Hartford Keith
NAME OF PREPARER
PHONE