

September 27, 1994

U. S. Nuclear Regulatory Commission
Document Control Desk
Mail Stop P1-37
Washington, D. C. 20555

Subject: River Bend Station - Unit 1
Docket No. 50-458
License No. NPF-47
River Bend Station Transient Methods Topical Report
(TAC M80315 and M84076)


File Nos.: G9.5, G9.42

RBG-40871
RBF1-94-0028

Entergy Operations, Inc. (EOI) held recent discussions with the NRC on July 20, 1994 and again on July 22 to address the last remaining issues pertaining to the River Bend Station Transient Methods Topical Report. The result of these discussions indicate that several issues remain to be resolved.

EOI has reviewed the changes required and has concluded that the level of effort needed to successfully address these changes is far greater than the benefits River Bend Station would derive from the report. The changes would adversely impact the benefits originally anticipated. Based on this finding and followup discussions with the NRC, EOI withdraws the River Bend Station Transient Methods Topical Report.

Please contact me if you have any questions.


James J. Fisicaro
Director-Nuclear Safety

*Acc'd
10*

River Bend Station Transient Methods Topical Report
RBG-40871
RBF1-94-0028
Page 2 of 2

cc: NRC Resident Inspector
P. O. Box 1051
St. Francisville, LA 70775

Mr. Raymond Azua
U. S. Nuclear Regulatory Commission
M/S OWFN 13-H-15
Washington, DC 20555

U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011