

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | S | L | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CON'T

0 1 | L | 5 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 5 | 0 | 0 | 3 | 1 | 2 | 8 | 3 | 0 | 4 | 1 | 1 | 8 | 3 | 9

REPORT SOURCE 30 31 DOCKET NUMBER 38 39 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing functional tests on the reactor trip breakers after

0 3 | they had been overhauled by the manufacturer, RPS matrix relay AB-5

0 4 | failed. Since the reactor was in the refueling mode, no action was

0 5 | required by Technical Specifications. There was no adverse affect

0 6 | on the health and safety of the public. This was the third event

0 7 | of this type. See LER's 47-82, 83-10.

0 8 |

0 9 |

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 19 VALVE SUBCODE 20

0 9 | I | A | 11 | E | 12 | A | 13 | R | E | L | A | Y | X | 14 | G | 15 | Z | 16

LER/RO REPORT NUMBER 17 EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 28 29 REPORT TYPE 30 REVISION NO. 32

0 9 | 8 | 3 | 0 | 1 | 5 | 0 | 3 | L | 0

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 ATTACHMENT SUBMITTED 40 NPD-4 FORM SUB. 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 44

0 9 | A | 13 | X | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | N | 24 | N | 25 | C | 3 | 4 | 5 | 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The plant I&C department is coordinating with Combustion Engineering and

1 1 | C.P. Clair Company concerning these relays. In addition, the failure of

1 2 | the C.P. Clair Model HZ2X-1011 mercury wetted relays has been referred

1 3 | to our engineering department for evaluation and formulation of future

1 4 | corrective action.

1 5 |

FACILITY STATUS 7 8 % POWER 9 10 OTHER STATUS 30 METHOD OF DISCOVERY 40 DISCOVERY DESCRIPTION 42

1 5 | H | 23 | 0 | 0 | 0 | 29 | NA | B | 31 | Operator observation

ACTIVITY CONTENT 11 12 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 26

1 5 | Z | 33 | Z | 34 | NA | NA

PERSONNEL EXPOSURES 36 37 38 39 DESCRIPTION 39

1 7 | 0 | 0 | 0 | 37 | Z | 39 | NA

PERSONNEL INJURIES 40 41 DESCRIPTION 41

1 7 | 0 | 0 | 0 | 40 | NA

LOSS OF OR DAMAGE TO FACILITY 42 43 DESCRIPTION 43

1 9 | Z | 42 | NA

PUBLICITY 44 45 DESCRIPTION 45

2 0 | N | 44 | NA

NAME OF PREPARER G. E. Walling PHONE: 305 465-3550 x3427