



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

April 15, 1983

Mr. J. G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III, 799 Roosevelt Road
Glen Ellyn, Illinois 60137


Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm a verbal report given to Mr. Neil DuBry of your staff at 1507 hours on this date. At that time, Mr. DuBry was advised that the Unit Two Control Room Cable Vault Halon System had been declared inoperable on April 14, 1983, following completion of a non-routine concentration test.

A followup report will be submitted within fourteen (14) days in accordance with Unit Two Technical Specifications, Section 6.9.1.12.

Sincerely,


W. G. Smith, Jr.
Plant Manager

WGS:frb

cc: J. E. Dolan
R. S. Hunter
M. P. Alexich
R. F. Kroeger
B. Germano
E. R. Swanson/N. E. DuBry, RO:III
R. C. Callen, MPSC
G. Charnoff, Esq.
J. M. Hennigan
R. O. Bruggee, EPRI
INPO
PNSRC
J. F. Stietzel
E. L. Townley
P. H. Jacques
Dir., IE (40 copies)
Dir., MIPC (4 copies)

8304220151 830415
PDR ADOCK 05000316
S PDR

IE22

APR 18 1983