

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

**SCE**

TELEPHONE  
(714) 492-7700

H. B. RAY

STATION MANAGER

April 14, 1983

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368


Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362  
30-Day Report  
Licensee Event Report No. 83-032 (Docket No. 50-361)  
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to Sections 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating Licenses NPF-10 and NPF-15 for San Onofre Units 2 and 3, respectively, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.7.5 associated with the Control Room Emergency Air Cleanup System (CREACUS). A single LER for the occurrence for Unit 2 is provided in accordance with NUREG-0161, since the occurrence involved a system shared between Units 2 and 3. Enclosed LER 83-032 addresses the event, including corrective actions to prevent recurrence.

Sincerely,



Enclosure (LER) 83-032

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)  
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)

8304220575 830414  
PDR ADDCK 05000361  
S PDR

IE-22  
83-171