

NO. 2-83-05/3L

This LER deals with the failure of the plant stack radiation monitor "B" sample pump. Applicable Tech. Spec. is 3.8.c.8.

U. S. NUCLEAR REGULATORY COMMISSION

[illegible]