

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

April 15, 1983

TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-14. This report concerns T.S. 3.3.3.8, "The radioactive liquid effluent monitoring instrumentation channels shown in Table 3.3-12 shall be operable...". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

H.B. Tucker / HBT

Hal B. Tucker

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

83 APR 25 A10:11

USNRC REGIONAL
ADMINISTRATOR