



Carolina Power & Light Company

P. O. Box 101, New Hill, North Carolina 27562
April 25, 1983

FILE: SH N-2/18
Item 124

MQAH 83-50

83 APR 29 AID: 12

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNITS 1 AND 2
DOCKET NOS. 50-400, 50-401
WELD DEFICIENCIES IN CLASS 1E TRANSFER PANELS

Dear Mr. O'Reilly:


This is to confirm the April 25, 1983 telephone conversation between Mr. N. J. Chiangi and Mr. A. Hardin. Mr. A. Hardin was informed that the April 1, 1983 potentially reportable item, pertaining to weld deficiencies in Class 1E Transfer Panels received from Systems Control, Inc., has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e).

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. G. Maxwell
Mr. V. Stello


N. J. Chiangi - Manager
Quality Assurance/Quality Control
Harris Plant

8305030601 830425
PDR ADOCK 05000400
S PDR

OFFICIAL COPY
IE 27