



May 2, 1983
PNS-LI-83-314-3

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-83-03

TURKEY POINT UNIT 4

DATE OF OCCURRENCE: APRIL 17 1983

TECHNICAL SPECIFICATION 6.9.2.a.9

FUEL ASSEMBLY X-04

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide prompt notification of the subject occurrence.

Very truly yours,

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (40)
Harold F. Reis, Esquire
File 933.1 TP

8305100251 830502
PDR ADDCK 05000251
S PDR

TE 22
PEOPLE...SERVING PEOPLE