

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33							
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE									

0	1	L	0	5	0	0	0	3	1	6	0	4	2	2	8	3	0	5	0	4	8	3	9										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30										
CON'T		REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 DURING PERFORMANCE OF 02-OHP-4030.STP.020, CMO-416 (CCW WEST HEAT EXCHANGER OUTLET
0 3 TO MISC. SERVICES VALVE) FAILED TO OPERATE WITHIN ISI TIME LIMITATIONS. THE VALVE
0 4 STOPPED IN AN INTERMEDIATE POSITION AND AN AUXILIARY EQUIPMENT OPERATOR HAD TO BE
0 5 SENT TO REOPEN CMO-416. THIS CONDITION WAS NONCONSERVATIVE WITH RESPECT TO
0 6 T.S.3.7.3.1 THE ACTION STATEMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT
0 7 AFFECTED. PREVIOUS OCCURRENCES: 82-007, 83-021 and 83-027.

0	9	W	B	E	B	V	A	L	V	E	X	B	D	8	3	0	4	0	0	3	L	0	X	X	Z	Z	0	0	0	0	N	N	A	C	1	8	2						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 3 THE VALVE PACKING AND BUSHINGS WERE LUBRICATED AND EXERCISED. THE VALVE TESTED
1 4 SATISFACTORILY AND RETURNED TO SERVICE. THE FREQUENCY OF ISI TESTING HAS BEEN
1 5 INCREASED FROM QUARTERLY TO MONTHLY INSPECTION. DURING THE NEXT OUTAGE OF
1 6 SUFFICIENT LENGTH CMO-416 WILL BE INSPECTED AND/OR REPAIRED.

1	5	E	1	0	0	NA	B	OPERATOR OBSERVATION	32														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION															
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																	
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION																	
PERSONNEL INJURIES		NUMBER		DESCRIPTION																			
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION																			
PUBLICATION		ISSUED		DESCRIPTION																			

8305120324 830504
PDR ADOCK 05000316
S PDR

NAME OF PREPARER D. ROBINSON

PHONE: 616-465-5901