



May 5, 1983

Log No. K83-691
File: RR 2 (NP-32-83-01)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Revision 2 to Licensee Event Report 83-012, including revised supplemental information pages. The revisions to the report are indicated by a "2" in the left margin of each page.

Please destroy your previous copies of this report and replace with the attached revision.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 40 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Tom Peebles
NRC Resident Inspector
Encl: 1 copy

8305130093 830505
PDR ADOCK 05000346
S PDR

MAY 11 1983

1E22