

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

April 28, 1983  
ANPP-23621-BSK/RQT

RECEIVED  
1983 MAY -4 PM 12:28  
REGIONAL

U. S. Nuclear Regulatory Commission  
Region V  
Creskide Oaks Office Park  
1450 Maria Lane - Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief  
Reactor Projects Branch 1

Subject: Deficiency Evaluation Report DER 83-18  
A 50.55(e) Evaluation Relating to  
The Installation of Pipe Supports Does Not Meet  
Seismic IX Requirements  
File: 83-019-026; D.4.33.2


Reference: Telephone Conversation between P. Stewart and G. Duckworth on  
March 29, 1983

Dear Sir:

The NRC was notified of the subject Deficiency Evaluation in the  
referenced telephone conversation, with a determination of reportability  
to be made within thirty (30) days (April 28, 1983).

The deficiency has subsequently been determined to be Not Reportable  
under the requirements of 10CFR50.55(e), therefore no written report is  
required. Necessary documentation of the evaluation will be maintained  
in APS files.

Very truly yours,



E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Projects Management  
ANPP Project Director

EEVB/RQT:db

cc: See Page 2

Mr. D. M. Sternberg  
ANPP-23621-RQT/BSK  
April 28, 1983  
Page 2

cc: Richard DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

T. G. Woods, Jr.  
G. C. Andognini  
J. A. Roedel  
D. B. Fasnacht  
A. C. Rogers  
B. S. Kaplan  
W. E. Ide  
J. Vorees  
J. R. Bynum  
D. D. Green  
P. P. Klute/D. D. Green  
A. C. Gehr  
W. J. Stubblefield  
W. G. Bingham  
R. L. Patterson  
R. W. Welcher  
R. M. Grant  
D. R. Hawkinson  
L. E. Vorderbrueggen  
G. A. Fiorelli

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339