

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

nm
H. B. RAY

STATION MANAGER

RECEIVED
NRC

MAY -8 PM 12:50

SCE

REGIONAL

TELEPHONE
(714) 492-7700

May 3, 1983

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator


Dear Sir:

Subject: Docket No. 50-362
30-Day Report
Licensee Event Report No. 83-035
San Onofre Nuclear Generating Station, Unit 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.3.3.7 associated with Fire Detection Instrumentation, and LCO 3.7.8.2 associated with the Fire Spray System. Enclosed LER 83-035 addresses this event.

If there are any questions regarding the above, please contact me.

Sincerely,



Enclosure: LER 83-035 (Unit 3)

8305160047 830503
PDR ADDCK 05000362
S PDR

IE-22
83-213

J. B. Martin

-2-

May 3, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)