

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

STATION MANAGER

May 3, 1983

RECEIVED
MAY 6 1983
SCE
12 37
TELEPHONE
(714) 492-7700

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361/362
Special Report (Docket No. 50-361)
Licensee Event Report No. 83-033 (Docket No. 50-362)
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to Section 3.7.8.2, Action Statement 'a' of Appendix A, Technical Specifications to Operating License NPF-10 for San Onofre Unit 2, and Section 6.9.1.13.b of Appendix A, Technical Specifications to Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required 30 day written report and copy of Licensee Event Report (LER) for an occurrence involving an inoperable fire spray system. Enclosed LER 83-033 for Unit 3, which also constitutes the required Special Report for Unit 2, addresses this event.

This report is delinquent because additional time was required to prepare a complete report.

If there are any questions regarding the above, please contact me.

Sincerely,



Enclosure: LER 83-033 (Unit 3)

8305160110 830503
PDR ADOCK 05000362
S PDR

IE-22
83-210

May 3, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)