



**LOUISIANA
POWER & LIGHT**


142 DELARONDE STREET * P.O. BOX 8008
NEW ORLEANS, LOUISIANA 70174-8008

(504) 386-2345

August 5, 1983

W3I83-0272
Q-3-A35.07.55

Mr. John T. Collins, Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 55
"Hold Up and Boric Acid Make Up Tanks
Incorrect Structural Calculations"

REFERENCE: LP&L letter W3I83-0220 dated June 23, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than August 5, 1983.

At the present time, the supporting documentation is under review and a Final Report is in preparation.

A Final Report will therefore be submitted to the USNRC by September 7, 1983.

Very truly yours,

F. J. Drummond
Manager Engineering & Technical Services

FJD/WAC/MAL;keh

cc: 1) Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

4) Mr. W. M. Stevenson

8308220252 830805
PDR ADOCK 05000382
S PDR

IE-27

110