


# VERMONT YANKEE NUCLEAR POWER CORPORATION



RD 5, Box 169, Ferry Road, Brattleboro, VT 05301

2.C.2.1  
FVY 83-91

REPLY TO:  
ENGINEERING OFFICE

1671 WORCESTER ROAD  
FRAMINGHAM, MASSACHUSETTS 01701  
TELEPHONE 617-872-8100

August 16, 1983

United States Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Office of Nuclear Reactor Regulation  
Mr. Domenic B. Vassallo, Chief  
Operating Reactors Branch No. 2  
Division of Licensing

References: (a) License No. DPR-28 (Docket No. 50-271)  
(b) Letter, VYNPC to USNRC, FVY 82-113, dated October 21, 1982

Subject: Supplemental Information Regarding Masonry Wall Design at  
Vermont Yankee (I&E Bulletin 80-11)

Dear Sir:

Per a telecon discussion with Mr. V. Rooney of your staff on August 2, 1983, we were requested to supply you with additional information regarding masonry wall design at our facility. The purpose of this letter is to inform you that on qualifying our masonry walls, joint reinforcement (i.e., Dur-O-Wall) was not used as a structural element to resist forces resulting from applied loads.

We trust that this information satisfies your concerns; however, should you have any other questions regarding this matter, please contact us.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

J. B. Sinclair  
Licensing Engineer

JBS/bt

8308220296 830816  
PDR ADOCK 05000271  
Q PDR

A001  
1/0