

NORTHEAST UTILITIES

THE CONNECTICUT LIGHT & POWER COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
HOLYOKE WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

General Offices • Selden Street, Berlin, Connecticut

P.O. BOX 270
HARTFORD, CONNECTICUT 06141-0270
(203) 665-6000

July 23, 1991

Docket No. 50-336

B13892

Re: ASME Section XI

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

Gentlemen:

Millstone Nuclear Power Station, Unit No. 2
Temporary Repair to X-182 Heat Exchanger Tube

In a letter dated June 28, 1991, ⁽¹⁾ Northeast Nuclear Energy Company submitted an informational letter pertaining to a temporary repair made to an X-182 heat exchanger tube at Millstone Unit No. 2.

Page 1, Section A, "Design Details," of the attachment to the above-referenced letter contains a typographical error that could lead to confusion. The pipe safety code class is stated to be "Class 1." It should read "Class 3."


We apologize for any inconvenience this error may have caused.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

FOR: E. J. Mroczka
Senior Vice President

BY:


E. A. DeBarba
Vice President

cc: T. T. Martin, Region I Administrator
G. S. Vissing, NRC Project Manager, Millstone Unit No. 2
W. J. Raymond, Senior Resident Inspector, Millstone Unit Nos. 1, 2, and 3

- (1) E. J. Mroczka letter to U.S. Nuclear Regulatory Commission, "Millstone Nuclear Power Station, Unit No. 2: Temporary Repair to X-182 Heat Exchanger Tube," dated July 28, 1991 (B13864).

9107290164 910723
PDR ADUCK 05000336
P FDR

A001
11/0