

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

026-416 917-926

NARRATIVE REPORT
FOR LER 50-366/1983-015

LICENSEE : GEORGIA POWER COMPANY
FACILITY NAME : EDWIN I. HATCH
DOCKET NUMBER : 50-366

Tech. Specs. section(s) which requires report:

This 14-day LER is required by Unit 2 Tech. Specs. Section 6.9.1.8., Item i.

Plant conditions at the time of the event(s):

Unit 2 was in cold shutdown for refueling.

Detailed description of the event(s):

On 4/27/83, while performing the "INSERVICE INSPECTION VISUAL EXAMINATION SURVEILLANCE PROCEDURE FOR CLASS 1, 2, AND 3 PIPE SUPPORTS" (HNP-907), inspecting personnel discovered that numerous pipe supports on the high pressure coolant injection (HPCI) pump discharge line were damaged. Damage varied from broken support plate welds to anchor bolts partially pulled out of structural concrete.

Consequences of the event(s):

This event had no effect on plant operation because the reactor was in cold shutdown mode at the time of this event.

Status of redundant or backup subsystems and/or systems:

There is no redundant or backup system for these supports.

Justification for continued operation:

No justification is needed for continued operation since Unit 2 is in cold shutdown for refueling.

If repetitive, number of previous LER:

This event is repetitive as last reported on LER 50-366/1981-104.

Impact to other systems and/or Unit:

This event had no impact on other Unit 2 systems. All Unit 1 HPCI pump discharge supports were visually inspected with satisfactory results.

Causes) of the event(s):

The cause of this event has not been determined.

Narrative Report for LER 50-366/1983-015
Page Two

Immediate Corrective Action:

The AE is performing an analysis of this event to determine corrective action.

Supplemental Corrective Action:

The pipe supports will be repaired as recommended by the AE prior to Unit 2 startup.

Scheduled (future) corrective action:

No future corrective action is anticipated following present repair.

Action to prevent recurrence (if different from corrective actions):

No further action is required to prevent recurrence.