

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
CON'T		REPORT SOURCE		DOCKET NUMBER		EVENT DATE		REPORT DATE																			

0	1	L	6	0	5	0	0	0	3	1	5	7	0	7	2	3	8	3	3	0	8	1	7	8	3	9	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | DURING REFUELING OPERATIONS, FIRE DOOR 373, TO THE ELEV. 587 VESTIBULE AREA

0 3 | WOULD NOT LATCH PROPERLY. THIS CONSTITUTED AN INOPERABLE PENETRATION FIRE BARRIER

0 4 | WHICH IS NONCONSERVATIVE WITH RESPECT TO T.S. 3.7.10. ACTION REQUIREMENTS WERE MET.

0 5 | PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURENCES INCLUDE: 82-022,

0 6 | 82-067, AND 83-073:

0 7 |

0 8 |

3	3	A	B	11	E	12	B	13	X	X	X	X	X	X	14	Z	15	Z	16	8	3	0	7	0	0	3	L	0	X	9	9	9	25						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40						
LER/SG REPORT NUMBER		EVENT YEAR		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 3 | THE BARREL RETAINING RING WAS FOUND BACKED OFF AND IN CONTACT WITH KNOB. THE RING

1 1 | WAS ADJUSTED AND THE SET SCREW TIGHTENED SECURELY. THE DOOR WAS SATISFACTORILY

1 2 | TESTED FOLLOWING REPAIRS.

1 3 |

1 4 |

1	5	H	28	0	0	0	29	NA	30	B	31	OPERATOR OBSERVATION	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20

1	5	Z	33	Z	34	NA	35	NA	36
7	8	9	10	11	12	13	14	15	16

1	7	0	0	0	37	Z	38	NA	39
7	8	9	10	11	12	13	14	15	16

1	3	0	0	0	40	NA	41	NA	42
7	8	9	10	11	12	13	14	15	16

1	3	Z	42	NA	43	NA	44	NA	45
7	8	9	10	11	12	13	14	15	16

2	3	N	44	NA	45	8308260148 830817	46	830817	47
7	8	9	10	11	12	PDR AD0CK 05000315	13	PDR	14

NAME OF PREPARER

R. H. PIEHL

PHONE:

616-465-5901