

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

SHIELDS L. DALTROFF  
VICE PRESIDENT  
ELECTRIC PRODUCTION

(215) 841-5001

August 16, 1983

Docket No. 50-278

I. E. Bulletin 80-13

Dr. Thomas E. Murley, Administrator  
Region 1  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406


Dear Dr. Murley:

An error has been discovered in our response to I.E. Bulletin No. 80-13 which was forwarded to your office on July 28, 1983. It has been noted that the first two lines of page 2 of the response have inadvertently been left out by our word processing system.

Attached is the proper response, which has been corrected to include the two missing lines.

If you have any questions, please do not hesitate to contact us.

Very truly yours,



Attachment

cc: A. R. Blough, Site Inspector  
Peach Bottom

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
Washington, D.C.