


THE CINCINNATI GAS & ELECTRIC COMPANY



CINCINNATI, OHIO 45201

June 28, 1983  
LOZ-83-0069

J. WILLIAMS, JR.  
SENIOR VICE PRESIDENT  
NUCLEAR OPERATIONS

Docket No. 50-358

U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Attention: Mr. J.G. Keppler  
Regional Administrator

Gentlemen:

RE: WM. H. ZIMMER NUCLEAR POWER STATION - UNIT 1  
10CFR50.55(e), ITEM M-44 - POSSIBLE  
OVERPRESSURIZATION OF PIPING  
W.O. 57300, JOB E-5590, FILE NO. 956C, M-44

This letter constitutes a supplement to our final report, QA-1777, dated May 25, 1982 concerning the subject deficiency initially reported to the Commission on April 30, 1982 under the requirements of 10CFR50.55(e).

In our previous response, QA-2172, dated December 20, 1983, we indicated that a relief valve would be installed between the inboard and outboard isolation valves, 1E12-F008 and 1E12-F009, by June 30, 1983. A revised schedule for completion of the corrective actions will be submitted upon the release from the NRC November 12, 1982 "Order to Show Cause and Order Immediately Suspending Construction" for work in this area.

8307080294 830628  
PDR ADOCK 05000358  
S PDR

1227  
JUL 5 1983  
1/0

Mr. J.G. Keppler  
Regional Administrator  
June 28, 1983  
LOZ-83-0069  
Page 2

We trust the above will be found acceptable as a supplement  
final report under 10CFR50.55(e).

Very truly yours,

THE CINCINNATI GAS & ELECTRIC COMPANY

By   
J.C. WILLIAMS, JR.  
SENIOR VICE PRESIDENT

DJS/JEC/sfr

cc: NRC Office of Inspection & Enforcement  
Washington, D.C. 20555  
NRC Senior Resident Inspector  
ATTN: W.F. Christianson  
NRC Zimmer Project Inspector, Region III  
ATTN: E. R. Schweibinz