



Consumers  
Power  
Company

James W Cook

Vice President - Projects, Engineering  
and Construction

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0453

September 8, 1983

Mr J G Keppler, Regional Administrator  
US Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER  
INSPECTION REPORT NO 50-329/83-11(OSC) AND 50-330/83-11(OSC)  
File: 0.4.2 UFI: 70\*01 Serial: CSC-6869  
0485.16 42\*05\*22\*04

REFERENCE: (1) R F Warnick letter to J W Cook, dated August 4, 1983  
Inspection Report No 50-329/83-11(OSC) and 50-330/83-11  
(OSC)

This letter, including Attachment 1, provides our response to Reference 1,  
which transmitted the subject Inspection Report and requested our  
written response to the item of noncompliance therein.

*James W. Cook*

JWC/BHP/dmh

Attachment

cc: RFWarnick, NRC Region III  
JJHarrison, NRC Region III  
RNGardner, NRC Region III  
RBLandsman, NRC Region III  
RJCook, NRC Senior Resident Inspector, Midland Site  
RLBurgess, NRC Resident Inspector, Midland Site

8309170083 830914  
PDR ADOCK 05000329  
Q PDR

NOV0783-0001A-CN02

SEP 12 1983



Consumers  
Power  
Company

James W Cook

Vice President - Projects, Engineering  
and Construction

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0453

September 8, 1983

Mr J G Keppler, Regional Administrator  
US Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER

INSPECTION REPORT NO 50-329/83-11(OSC) AND 50-330/83-11(OSC)

File: 0.4.2      UFI: 70\*01      Serial: CSC-6869  
0485.16      42\*05\*22\*04

REFERENCE: (1) R F Warnick letter to J W Cook, dated August 4, 1983  
Inspection Report No 50-329/83-11(OSC) and 50-330/83-11  
(OSC)

This letter, including Attachment 1, provides our response to Reference 1,  
which transmitted the subject Inspection Report and requested our  
written response to the item of noncompliance therein.

*James W. Cook*

JWC/BHP/dmh

Attachment

cc: RFWarnick, NRC Region III  
JJHarrison, NRC Region III  
RNGardner, NRC Region III  
RBLandsman, NRC Region III  
RJCook, NRC Senior Resident Inspector, Midland Site  
RLBurgess, NRC Resident Inspector, Midland Site

8309170083 830914  
PDR ADOCK 05000329  
Q PDR

NOV0783-0001A-CN02

SEP 12 1983

2. Corrective Action to be Taken to Avoid Further Noncompliance:

Dedicated crews of craftsmen were established July 20, 1983, to maintain the laydown area in accordance with the requirements of FPG 4.000.

Additional supervision has been added at the Poseyville laydown area to direct the crews and implement access control for entrance into the laydown area.

3. The Date When Full Compliance Will be Achieved:

Full compliance has been achieved.

All the items identified in the Notice of Violation were placed on dunnage June 21, 1983. The unistrut pieces were subsequently moved to the scrap area for salvage on July 23, 1983.

The manning of the dedicated crews and additional supervision have been completed and are presently functioning.

Attachment 1  
Serial: CSC-6869

CONSUMERS POWER COMPANY'S RESPONSE TO  
US NUCLEAR REGULATORY COMMISSION, REGION III  
INSPECTION REPORT NO 50-329/83-11(OSC) & 50-330/83-11(OSC)

Appendix (Notice of Violation) to Inspection Report No. 50-329/83-11(OSC) and 50-330/83-11(OSC) provides one item of noncompliance to 10 CFR 50, Appendix B. The NRC statement and our responses are given below:

NRC STATEMENT

10 CFR 50, Appendix B, Criterion V states, in part, "Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, or a type appropriate to the circumstances and shall be accomplished in accordance with these instructions, procedures, or drawings."

CPC-1-A Policy 13, Handling, Storage, and Shipping; Section 3.3, RECEIPT AND STORAGE, states, in part, "Suppliers provide plans, . . . , procedures and personnel to . . . , store, . . . items upon arrival at the site."

Bechtel Power Corporation field Procedure FPG 4.000, Revision 10, Storage - Maintenance/Inspection of Equipment and Materials, states in part in Section 6.2.4 "Items shall be stored on dunnage or cribbing to allow for air circulation and to minimize the trapping of water."

Contrary to the above, structural items stored in various areas of the Poseyville Road laydown area were not stored on dunnage or cribbing to allow for air circulation and to minimize the trapping of water as required by Bechtel Field Procedure FPG 4.000, Revision 10.

This is a Severity Level V violation (Supplement II).

CONSUMERS POWER COMPANY RESPONSE

In accordance with this Notice of Violation, an explanation of corrective action is as follows:

1. Corrective Action Taken and the Results Achieved:

As clarification to the item of noncompliance the structural I-beam identified in your report was intended for use as a pipe storage rack and was a spare setting alongside others being used as such.

Work orders for placing on dunnage the stock steel and unistrut pieces welded to base plates were issued June 20, 1983, and June 7, 1983, respectively. The work was completed June 21, 1983, and verified by CPCo.

CONSUMERS POWER COMPANY  
Midland Units 1 and 2  
Docket No 50-329/50-330

Letter Serial CSC- Dated September 8, 1983

At the request of the Commission and pursuant to the Atomic Energy Act of 1954, and the Energy Reorganization Act of 1974, as amended and the Commission's Rules and Regulations thereunder, Consumers Power Company submits the response to R F Warnick letter to J W Cook dated August 4, 1983.

CONSUMERS POWER COMPANY

By JW Cook  
J W Cook, Vice President  
Projects, Engineering and Construction

Sworn and subscribed before me this 8 day of September, 1983.

Barbara L. Lunsford  
Notary Public

My Commission Expires September 8, 1984



OL/OM SERVICE LIST

Mr Charles Bechhoefer, Esq  
Administrative Judge  
Atomic Safety & Licensing Board Panel  
US Nuclear Regulatory Commission  
Washington, DC 20555

Dr Frederick P Cowan  
Administrative Judge  
6152 N Verde Trail  
Apt B-125  
Boca Raton, FL 33433

Mr Michael Miller, Esq  
Isham, Lincoln & Beale  
3 First National Plaza  
Suite 5200  
Chicago, IL 60602

Mr D F Judd, Sr Project Manager  
The Babcock & Wilcox Company  
P O Box 1260  
Lynchburg, Va 24505

Atomic Safety & Licensing Board Panel  
U S Nuclear Regulatory Commission  
Washington, DC 20555

Atomic Safety & Licensing Appeal Board  
U S Nuclear Regulatory Commission  
Washington, DC 20555

Mr William D Paton, Esq  
Counsel for NRC Staff  
US Nuclear Regulatory Commission  
Washington, DC 20555

Ms Barbara Stamiris  
5795 North River Road  
Route 3  
Freeland, MI 48623

Dr Jerry Harbour  
US Nuclear Regulatory Commission  
Atomic Safety & Licensing Board Panel  
Washington, DC 20555

Mr Frank J Kelley, Esq  
Attorney General of the  
State of Michigan  
Mr Stewart H Freeman, Esq  
Assistant Attorney General  
Environmental Protection Div  
720 Law Building  
Lansing, MI 48913

Mr Myron M Cherry, Esq  
Cherry & Flynn  
3 First National Plaza  
Suite 3700  
Chicago, IL 60602

Mr Wendell H Marshall  
RFD 10  
Midland, MI 48640

Mr John DeMeester  
Dow Chemical Building  
Michigan Division  
Midland, MI 48640

Ms Mary Sinclair  
5711 Summerset Street  
Midland, MI 48640

Mr Steve Gadler  
2120 Carter Avenue  
St Paul, MN 55108

Mr Lee L Bishop  
Harmon & Weiss  
1725 I Street, NW #506  
Washington, DC 20006

Mr C R Stephens  
Docketing and Service Station  
Office of the Secretary  
US Nuclear Regulatory  
Washington, DC 20555

Lynn Bernabei  
Governmental Accountability  
Project (GAP)  
1901 Q Street NW  
Washington, DC 20009